

APLICACIÓN: **Super-Kool™** es un limpiador para todo tipo de máquinas de hielo, fácil de usar y efectivo. Contiene una combinación de sustancias concentradas: ácidos, inhibidores y secuestrantes, formulado específicamente para remover el exceso de minerales y suciedad. Es seguro de usar en cualquier tipo de máquinas de hielo, incluyendo aquellas con tambores de níquel y evaporadores de aluminio. **Super-Kool** tiene un sistema de ácido secuestrante único, el cual convierte de una manera segura el agua dura y estancada en compuestos solubles, que se eliminan fácilmente de la máquina sin necesidad de conectar líneas o drenar orificios. **Super-Kool** es además económico y fácil de usar. Su alta tasa de dilución y la rápida acción de disolución, ahorra tiempo, trabajo y materiales.

INSTRUCCIONES:

1. Usar protección en ojos y piel, cuando se mezclen y apliquen las sustancias.
2. Apague la refrigeración y la bomba de circulación.
3. Drenar la máquina y llenarla con agua limpia.
4. Agregar 8 onzas de **Super-Kool** por cada 3 galones de capacidad de agua.
5. Encender únicamente la bomba de circulación, dejarla funcionando por 30 minutos.
6. Luego de la limpieza, drenar todas las sustancias y enjuagar completamente con agua fresca.
7. Llenar con agua fresca y encender. Desechar el primer ciclo de hielo.

Nota: Una solución de 8 onzas de **Super-Kool** por galón de agua es efectiva en la limpieza de las partes que no están en contacto de sustancias circulantes.

INGREDIENTES: Ácido Fosfórico (CAS# 7664-38-2)

¡PELIGRO! Causa quemaduras graves en la piel y daño en los ojos.

Mantener fuera del alcance de los niños. Leer la etiqueta antes de usar. No respirar el vapor o vaho. Lavar la piel meticulosamente después de la manipulación. Usar guantes de protección de caucho, nitrilo o de neopreno, así como ropa y gafas de seguridad o careta para proteger los ojos y el rostro. Guardar bajo llave. Eliminar el contenido y contenedor en las instalaciones apropiadas, de conformidad con las leyes federales, estatales y locales. Para información adicional, consulte la Hoja de Datos de Seguridad (SDS).

PRIMEROS AUXILIOS / RESPUESTA:

EN CASO DE INGESTIÓN: Enjuagar la boca. NO provocar el vómito, llamar de inmediato a un centro de control de envenenamientos o a un médico. Para información adicional, consulte la Hoja de Datos de Seguridad (SDS). **AL CONTACTO CON LA PIEL (o pelo):** Quitarse de inmediato la ropa contaminada. Enjuagar la piel con agua y jabón durante un mínimo de quince minutos. Si hay quemaduras, llame inmediatamente a un centro de control de envenenamientos o a un médico. Lavar la ropa contaminada antes de usarla nuevamente.

EN CASO DE INHALACIÓN: Transportar a la víctima al exterior y mantenerla en reposo en una posición en la que pueda respirar cómodamente. Llamar inmediatamente a un centro de control de envenenamientos o a un médico. **AL CONTACTO CON LOS OJOS:** Enjuagar meticulosamente con agua durante varios minutos. Si tiene lentes de contacto y resulta fácil de hacer, quitarlos. Seguir con el enjuague. Llamar inmediatamente a un centro de control de envenenamientos o a un médico.

Este producto no es inflamable. Utilizar polvo químico seco, dióxido de carbono, espuma u otros medios adecuados en caso de incendio.

NO GARANTIZADO: Este producto se proporciona "tal cual". El vendedor declara expresamente de todas y cada una de las garantías, ya sean expresa, implícita, legal o de otra manera y renuncia específicamente a toda garantía implícita, incluyendo sin limitación, cualquier garantía implícita de comerciabilidad o idoneidad para un propósito particular o las derivadas por la razón de la costumbre o el uso en el comercio o por los usos habituales.

FABRICADO EN USA

Servicio al cliente: 800.995.2222
Emergencias químicas: 800.255.3924

DIVERSITECH
PRODUCT NO.
SUPER-KOOL-16

Accessories

Super-Kool™

Nickel-safe ice machine cleaner

- Removes mineral and soil deposits
- Easy to apply
- Works on all ice machines
- Economical and effective

ANGER! Causes severe skin burns and eye damage.



APPLICATION: **Super-Kool™** is an effective and easy to use cleaner for all ice machines. It contains a concentrated combination of acids, inhibitors and sequestrants formulated to dissolve mineral and soil deposits. It is safe for use on all types of ice machines including those with nickel drums and aluminum evaporators. **Super-Kool** has a unique acid sequestrant system which safely converts hard water scale to soluble compounds which are easily flushed out of the system without plugging lines and stopping up orifices. **Super-Kool** is also economical and easy to apply. Its high dilution rate and fast-dissolving action save time, labor and materials.

DIRECTIONS:

1. Wear eye and skin protection when mixing and applying solutions.
2. Turn off refrigeration and circulation pump.
3. Drain machine and refill with clean water.
4. Add 8 ounces of **Super-Kool** for every 3 gallons of water capacity.
5. Turn on circulation pump only. Allow to circulate for 30 minutes.
6. After cleaning, drain all solutions and flush completely with fresh water.
7. Refill with fresh water and return to operation. Discard the first ice cycle.

Note: A solution of 8 ounces of **Super-Kool** per gallon of water is effective for cleaning parts not contacted by circulating solution.

CONTAINS: Phosphoric Acid CAS# 7664-38-2

DANGER! Causes severe skin burns and eye damage. Keep out of reach of children. Read label before use. Do not breathe mist or spray. Wash skin thoroughly after handling. Wear rubber, nitrile or neoprene protective gloves and clothing, and safety goggles or face shield to protect eyes and face. Store locked up. Dispose of contents and container to appropriate facility in accordance with Federal, State, and local regulations. For additional information, consult the Safety Data Sheet (SDS).

FIRST AID: IF SWALLOWED: Rinse mouth. Do NOT induce vomiting, immediately call a POISON CENTER or doctor. For additional information, consult the Safety Data Sheet (SDS). **IF ON SKIN (or hair):** Remove immediately all contaminated clothing. Rinse SKIN with water/shower for a minimum of fifteen minutes. If burns are present, immediately call a POISON CENTER or doctor. Wash contaminated clothing before reuse. **IF INHALED:** Remove victim to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or doctor. **IF IN EYES:** Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor.

This product is not flammable. Use dry chemical, carbon dioxide, foam or other media suitable for the primary source of the fire.

NON-WARRANTY: This product is provided "as is." Seller specifically disclaims any and all warranties, whether expressed, implied, statutory or otherwise and specifically disclaims all implied warranties including without limitation, any implied warranties of merchantability or fitness for a particular purpose or those arising by reason of custom or usage in the trade or by course of dealing.

MADE IN USA

DOC32507

DiversiTech Corporation
6650 Sugarloaf Parkway
Duluth, GA 30097
www.diversitech.com
800.995.2222
878-542-3600
For Customer Service
800.255.3924
For Chemical Emergencies

0

95247114992

6

Net Contents: 16 oz. (473.1 ml.)