

IMPORTANT NOTE: THE INSTALLER IS RESPONSIBLE FOR THETHERING AND BOLTING UNITS TO WITHSTAND WIND


<sup>NO.</sup>QUICK SLING STAND - 4001 MODEL NO. QSTD4001

GMS. REV.

WEIGHT

|A|

В



	DESCRIPTION	Default/ QTY.
0	Angle Iron Stand 12 J-Bar	4
8	Angle Iron Stand Extension Bar	2
1	Iron Stand 23in Angle Iron Arm	2
7	1/4-20x1/2in Zinc Hex Bolts	8
8	1/4in Bonded Washers	8
7	Angle Iron Stand 6x6 Feet	4
5	6x1.5 - Mini Split Rubber Foot	8
0	3/8-16x2in Carriage Bolt Zinc	4
4	3/8in Bonded Washer	4
2	3/8in Zinc Hex Nut	8
9	3/8-16x1 3/4in Hex Bolt Galv	4
3	3/8in Split Washer Galv	4
1	3/8in Galvanized Hex Nuts	4

## NOTE - ALL ASSEMBLY HARDWARE IS INCLUDED

 CONFIDENTIAL - PROPRIETARY - DO NOT COPY

 THE INFORMATION SET FORTH IN THIS DOCUMENT AND REWTER OF DIVERSIFICH
 WEIGHT
 WEIGHT

 INFORMATION SET FORTH IN THIS DOCUMENT AND REWTER OF DIVERSIFICH
 WEIGHT
 GMS.

 BURG. NO.
 QUICK SLING STAND - 4001
 REV.

 DO NOT SCALE DRAWING
 MODEL NO. QSTD4001
 REV.

 $2^{\text{SHEET}}$