



ITEM NO.	PART NUMBER	DESCRIPTION	Default/ QTY.
1	MNT-A10-02-367	Angle Iron Stand 18 J-Bar	4
2	MNT-A10-03-365	Angle Iron Stand Extension Bar	2
3	MNT-A10-02-368	Iron Stand 27in Angle Iron Arm	2
4	MNT-A10-04-354	1/4-20x1/2in Zinc Hex Bolts	8
5	MNT-A10-04-355	1/4in Bonded Washers	8
6	MNT-A10-03-364	Angle Iron Stand 6x6 Feet	4
7	MNT-A10-04-362	6x1.5 - Mini Split Rubber Foot	8
8	MNT-A10-04-357	3/8-16x2in Carriage Bolt Zinc	4
9	MNT-A10-04-361	3/8in Bonded Washer	4
10	MNT-A10-04-359	3/8in Zinc Hex Nut	8
11	MNT-A10-04-356	3/8-16x1 3/4in Hex Bolt Galv	8
12	MNT-A10-04-360	3/8in Split Washer Galv	8
13	MNT-A10-04-358	3/8in Galvanized Hex Nuts	8
14	MNT-A10-02-369	Iron Stand 27in Stability Arm	2

NOTE - ALL ASSEMBLY HARDWARE IS INCLUDED

| NCHES | MILLIMETERS | X = ±0.1 | [X = ±2.5] | .XX = ±0.01 | .X = ±1.3 | .XXX = ±0.005 | .XX = ±0.13 |





CONFIDENTIAL - PROPRIETARY - DO NOT COPY	MATE
THE INFORMATION SET FORTH IN THIS DOCUMENT AND RELATED	
INFORMATION IS THE CONFIDENTIAL PROPERTY OF DIVERSITECH CORPORATION, AND IS NOT TO BE COPIED OR REPRODUCED OR DISTRIBUTED IN ANY FORM WITHOUT PRIOR WRITTEN PERMISSION FROM DIVERSITECH CORPORATION.	DWG.
DO NOT SCALE DRAWING	
DESCRIPTION	

	MATERIAL:	WEIGHT
	DWG. NO	GMS.
	dwg. no. Quick sling stand -5002	REV.
	model no. Qstd5002	
		SHEET

2 of 2